




Diesel Parts

—Nozzle



Tianjin Geortor Auto Parts Co., Ltd.













2-1-1703, Luolan Garden, YongAn Rd. Hexi Dist. Tianjin, China.


Web-site: www.gerotorauto.com E-mail: info@gerotorauto.com

Tel: 0086-22-23286383

Fax: 0086-22-83863296


O.E.M names and numbers are used for reference purpose only.

 <p>Pictures coming soon</p> <p>75 0003</p> <p><i>Replacing</i> L097PBD DSLA150FL097</p> <p><i>Servicing</i> HYUNDAI TERRACAN 2.9 CRDI KIA CARNIVAL 2.9 CRDI SEDONA 2.9 CRDI</p>	 <p>Pictures coming soon</p> <p>75 0004</p> <p><i>Replacing</i> L087PBD DSLA144FL087</p> <p><i>Servicing</i> DACIA LOGAN 1.5 DCI NISSAN MICRA 1.5 DCI RENAULT SUZUKI JIMNY 1.5</p>	 <p>Pictures coming soon</p> <p>75 0005</p> <p><i>Replacing</i> L120PBD</p> <p><i>Servicing</i> Renault Clio Mk II 1.5 DCI</p>
 <p>Pictures coming soon</p> <p>75 0006</p> <p><i>Replacing</i> L121PBD DLLA150FL121</p> <p><i>Servicing</i> FORD TRANSIT 1.8 TDCI</p>	 <p>Pictures coming soon</p> <p>75 0025</p> <p><i>Replacing</i> L025PBC 152FL025</p> <p><i>Servicing</i> Volvo</p>	 <p>Pictures coming soon</p> <p>75 0028</p> <p><i>Replacing</i> L028PBC 152F028</p> <p><i>Servicing</i> VOLVO</p>
 <p>Pictures coming soon</p> <p>75 0052</p> <p><i>Replacing</i> L052PBC 20547351</p> <p><i>Servicing</i> VOLVO</p>	 <p>Pictures coming soon</p> <p>75 0060</p> <p><i>Replacing</i> L060PBA DSLA140P5503</p> <p><i>Servicing</i> PERKINS 1004 40T 1006 60T MASSEY FERGUSON MF3350 3355 4235 4245 6180 LANDINI ATLAS 100</p>	 <p>Pictures coming soon</p> <p>75 0070</p> <p><i>Replacing</i> 105017-0070 DLLA154PN007 9432610027</p> <p><i>Servicing</i> MAZDA</p>
 <p>Pictures coming soon</p> <p>75 0080</p> <p><i>Replacing</i> 0434250110 DN0SD240</p> <p><i>Servicing</i> Mercedes-benz</p>	 <p>Pictures coming soon</p> <p>75 0096</p> <p><i>Replacing</i> L096PBD DSLA153FL096</p> <p><i>Servicing</i> FORD MONDEO III 2.0 TDCI 2001 - PRESENT</p>	 <p>Pictures coming soon</p> <p>75 0109</p> <p><i>Replacing</i> L109PBD DSLA146FL109</p> <p><i>Servicing</i> FORD TRANSIT, SUZUKI LIANA, CITROEN C3</p>

**75 0128**


Replacing L128PBD
EJDR00402Z

Servicing FORD MONDEO III 2.0
16V TDDI/TDCI 2001 -
PRESENT

**75 0130**


Replacing L130PBA
2645K611

Servicing Perkins

**75 0131**


Replacing L131PBA
2645K613

Servicing Perkins

**75 0133**


Replacing L133PBD
DSLA154FL133

Servicing TRANSIT 2L TDCI
JAGUAR X TYPE 2.0D
2000 - 2007

**75 0134**


Replacing L134PBD
DSLA154FL134

Servicing FORD MK3 TDCI

**75 0136**


Replacing L136PBD
DSLA156FL136

Servicing HYUNDAI TERRACAN 2.9 CRDI
4WD 2003 - PRESENT KIA BONGO
2.9 CRDI 2001 - PRESENT
FRONTIER 2.9 CRDI 2003 -
PRESENT PREGIO 2.9 CRDI 2001
- PRESENT

**75 0137**


Replacing L137PBD
DSLA158FL137

Servicing KIA CARNIVAL II 2.9 2005
- PRESENT, SEDONA II 2.9
2001 - PRESENT

**75 0138**


Replacing L138PBD
DSLA146FL138

Servicing SSANGYONG KYRON 2.7
2005 - PRESENT REXTON 2.7
2003 - PRESENT
RODIUS/STAVIC 2.7 2004 -
PRESENT

**75 0145**


Replacing L145PBD
DSLA154FL145

Servicing FORD TRANSIT 2.4 TDCI
RWD 2004 - PRESENT

**75 0146**


Replacing L146PBD

Servicing Renault Kangoo, Modus

**75 0150**













Replacing L150PBD


Servicing

**75 0157**

Replacing L157PBD
DSLA148FL157

Servicing SSANGYONG ACTYON
2.0 2006 - PRESENT
KYRON 2.0 2006 -
PRESENT

 <p>Pictures coming soon</p> <p>75 0159</p> <p><i>Replacing</i> L159PBA</p> <p><i>Servicing</i> PERKINS GENERATOR 80 -107BHP</p>	 <p>Pictures coming soon</p> <p>75 0216</p> <p><i>Replacing</i> L216PBC</p> <p><i>Servicing</i> VOLVO D13A400</p>	 <p>Pictures coming soon</p> <p>75 0221</p> <p><i>Replacing</i> L221PBC DEL-PDE</p> <p><i>Servicing</i> VOLVO</p>
 <p>Pictures coming soon</p> <p>75 0222</p> <p><i>Replacing</i> L222PBC DEL-PDE</p> <p><i>Servicing</i> VOLVO B12, FH12, FM12 FM 9, NH12</p>	 <p>Pictures coming soon</p> <p>75 0223</p> <p><i>Replacing</i> L223PBC</p> <p><i>Servicing</i> CASE IH, VOLVO PENTA, VOLVO FM9</p>	 <p>Pictures coming soon</p> <p>75 0252</p> <p><i>Replacing</i> PF064</p> <p><i>Servicing</i> IFA L60</p>
 <p>Pictures coming soon</p> <p>75 0253</p> <p><i>Replacing</i> 016253 SE170-66-11</p> <p><i>Servicing</i> IFA W50</p>	 <p>Pictures coming soon</p> <p>75 0256</p> <p><i>Replacing</i> 341967150 DOP140S435-4369</p> <p><i>Servicing</i> TATRA T-815</p>	 <p>Pictures coming soon</p> <p>75 0257</p> <p><i>Replacing</i> DSL150S428-1416 93009306</p> <p><i>Servicing</i> URSUS C-385</p>
 <p>Pictures coming soon</p> <p>75 0258</p> <p><i>Replacing</i> DSL150S525-1441 93009305</p> <p><i>Servicing</i> URSUS C-385</p>	 <p>Pictures coming soon</p> <p>75 0259</p> <p><i>Replacing</i> DSL150S535-1417 93009307</p> <p><i>Servicing</i> URSUS C385</p>	 <p>Pictures coming soon</p> <p>75 0260</p> <p><i>Replacing</i> 930558 DOP160S430-1436</p> <p><i>Servicing</i> ZETOR</p>




Pictures coming soon

75 0261

Replacing HSL150F38

Servicing MF-3




Pictures coming soon

75 0262

Replacing HSL150F42

Servicing MF-4




Pictures coming soon

75 0263

Replacing DSL138A3

Servicing BIZON SW400 LEYLAND




Pictures coming soon

75 0264

Replacing 0433270114
DLL150S393
BDLL150S6501

Servicing FENDT




Pictures coming soon

75 0265

Replacing DSL150A2
50508730

Servicing URSUS C355 C360




Pictures coming soon

75 0266

Replacing D1Z1F42
50004460

Servicing URSUS C330 C325 C328




Pictures coming soon

75 0291

Replacing L291PRD

Servicing Renault




Pictures coming soon

75 0330

Replacing 293400-0330
G3S33

Servicing Toyota Dyna, Hiace, Hilux




Pictures coming soon

75 0337

Replacing 105015-3370
DLLA168S304NP59

Servicing Audi, BMW, Ford, Iveco,
Opel, Toyota, Volvo, VW,
Yanmar




Pictures coming soon

75 0532

Replacing 093400-5320
DN20PD32

Servicing




Pictures coming soon

75 0564

Replacing 093400-8640
DLLA145P864
23670-09060

Servicing TOYOTA HILUX HIACE
2KD PICKUP VIGO
















Pictures coming soon

75 0747

Replacing 093400-7470
DLLA147P747


Servicing TOYOTA RAV4 II 2.0 D-4D
2000 – 2005

 <p>Pictures coming soon</p> <p>75 0765</p> <p><i>Replacing</i> 093400-7650 DLLA148P765</p> <p><i>Servicing</i> NISSAN X-TRAIL(T30) 2.2 DI 4X4 16600-8H800</p>	 <p>Pictures coming soon</p> <p>75 0788</p> <p><i>Replacing</i> 093400-7880 DLLA147P788</p> <p><i>Servicing</i> Toyota Dyna, Hiace, Hilux</p>	 <p>Pictures coming soon</p> <p>75 0842</p> <p><i>Replacing</i> 093400-8420 DLLA155P842</p> <p><i>Servicing</i> HINO J08</p>
 <p>Pictures coming soon</p> <p>75 0844</p> <p><i>Replacing</i> 093400-8440 DLLA158P844</p> <p><i>Servicing</i> Isuzu 4KH1 Engine</p>	 <p>Pictures coming soon</p> <p>75 0848</p> <p><i>Replacing</i> 093400-8480 DLLA155P848</p> <p><i>Servicing</i> HINO J05, 500 Series, Kobelco Excavator</p>	 <p>Pictures coming soon</p> <p>75 0852</p> <p><i>Replacing</i> 093400-8520 DLLA142P852</p> <p><i>Servicing</i> ISUZU D-MAX 3.0L</p>
 <p>Pictures coming soon</p> <p>75 0854</p> <p><i>Replacing</i> 093400-8540 DLLA158P854</p> <p><i>Servicing</i> ISUZU N SERIES N- SERIES 5.2 4HK1 2004 – PRESENT</p>	 <p>Pictures coming soon</p> <p>75 0861</p> <p><i>Replacing</i> 093400-8610 DLLA155P807</p> <p><i>Servicing</i> Mitsubishi Canter</p>	 <p>Pictures coming soon</p> <p>75 0863</p> <p><i>Replacing</i> 093400-8630 DLLA155P863</p> <p><i>Servicing</i> HILUX 3.0 D4D, TOYOTA LAND CRUISER (PRADO)</p>
 <p>Pictures coming soon</p> <p>75 0865</p> <p><i>Replacing</i> 093400-8650 DLLA152P865</p> <p><i>Servicing</i> ISUZU 4HK1-T, 6WF1-TC</p>	 <p>Pictures coming soon</p> <p>75 0870</p> <p><i>Replacing</i> 093400-8700 DLLA145P870</p> <p><i>Servicing</i> MITSUBISHI L200 2.5, PAJERO SPORT II 2006 – PRESENT</p>	 <p>Pictures coming soon</p> <p>75 0872</p> <p><i>Replacing</i> 093400-8720 DLLA148P872</p> <p><i>Servicing</i> NISSAN Navara D40, Pathfinder R51</p>

**75 0876**


Replacing 105015-8760
DLLA150SN876

Servicing Nissan FE6T Engine

**75 0880**


Replacing 093400-8800
DLLA155P1025

Servicing TOYOTA HILUX 3.0 D 2006 -
2007 HILUX 2.5 D 2006 - 2007
LANDCRUISER 3.0 D 2006 -
2007

**75 0884**


Replacing 093400-8840
DLLA153P884

Servicing CITROEN JUMPER 2.2 HDI 2006 -
PRESENT RELAY 2.2 HDI 2006 -
PRESENT LAND ROVER
DEFENDER 2006 - PRESENT
FORD TRANSIT 2.2 TDCI 2006 -
PRESENT PEUGEOT BOXER 2.2
HDI 2006 - PRESENT

**75 0885**


Replacing 093400-8850
DLLA153P885

Servicing Ford Transit, Land Rover
Defender

**75 0941**


Replacing 093400-9410
DLLA155P941

Servicing Toyota DYNA 200 HINO
N04C Euro 4

**75 0947**


Replacing 093400-9470
DLLA152P947

Servicing NISSAN NAVARA 2.5 DCI
2006 - PRESENT,
PATHFINDER 2.5 DCI
2006 - PRESENT

**75 1024**


Replacing 093400-1024
DLLA145P1024

Servicing TOYOTA HILUX HIACE
2KD PICKUP VIGO

**75 1032**


Replacing 0433171032
DLLA150P31
468826

Servicing VOLVO, Mercedes-Benz
Trucks

**75 1036**


Replacing 0433271036
DLLA150S720

Servicing VOLVO UTB650

**75 1042**


Replacing 0433271042
DLLA23S179
51 10102 0013

Servicing MAN

**75 1043**

Replacing 0433271043
DLLA150S178
240339


Servicing VOLVO

**75 1045**

Replacing 0433172045
DLLA144P1707


Servicing DONG FENG CUMMINS
ISLe375_30_EU3

Nozzle


75 1046

Replacing 0433271045
DLLA150S186

Servicing Mercedes-benz OM355


75 1047


Replacing 0433172047
DLLA142P1709

Servicing DONGFENG CUMMINS

75 1048


Replacing 0433271046
DLLA150S187

Servicing MERCEDES-BENZ


75 1052

Replacing 0433171052
DLLA150P52
1545153

Servicing VOLVO PENTA, BM


75 1062


Replacing 093400-1062
DLLA155P1062

Servicing HILUX 3,0L D4D

75 1081


Replacing 0433171703
DLLA152P1081
1693747

Servicing DAF


75 1084

Replacing 0433171084
DLLA142P87
349701

Servicing SCANIA


75 1096


Replacing 093400-1096
DLLA158P1096

Servicing ISUZU 4HK1/6HK1

75 1097


Replacing 093400-1097
DLLA158P1097

Servicing ISUZU 6WF1-TC


75 1100


Replacing 0433171100
DLLA150P110
424531

Servicing VOLVO, VOLVO PENTA


75 1108


Replacing 0433171108
DLLA150P119

Servicing VOLVO, VOLVO PENTA


75 1117


Replacing 0433171117
DLLA150P91
369289

Servicing SCANIA

**75 1130**


Replacing 0433171130
 DLLA144P144
 380808

Servicing SCANIA

**75 1134**


Replacing 0433171134
 DLLA148P149
 470934

Servicing VOLVO B12, F12, NL12,
 VOLVO BM, VOLVO
 PENTA

**75 1146**


Replacing 0433171146
 DLLA148P163
 589745

Servicing DAF F1100 1300 1700
 1900

**75 1156**


Replacing 0433171156
 DLLA150P177
 422955

Servicing VOLVO F10, NL10

**75 1157**


Replacing 0433171157
 DLLA150P178
 422951

Servicing VOLVO B10, B58, F10,
 FL10, FS10, NL10

**75 1159**


Replacing 0433171159
 DLLA134P180
 51 10102 0202

Servicing MAN

**75 1165**


Replacing 0433171165
 DLLA146P154
 1107960

Servicing SCANIA

**75 1169**


Replacing 0433171169
 DLLA146P203

Servicing MAN

**75 1174**


Replacing 0433171174
 DLLA144P184
 51 10102 0201

Servicing MAN

**75 1180**


Replacing 0433171180
 DLLA142P221
 1304240

Servicing SCANIA

**75 1188**













Replacing 0433171188
 DLLA155P230
 1302563


Servicing SCANIA

**75 1214**

Replacing 0433171214
 DLLA146P166
 51101020215


Servicing MAN

 <p>Pictures coming soon</p> <p>75 1221</p> <p><i>Replacing</i> 0433171221 DLLA155P306 1327377</p> <p><i>Servicing</i> SCANIA</p>	 <p>Pictures coming soon</p> <p>75 1222</p> <p><i>Replacing</i> 0433171222 DLLA155P307 1327375</p> <p><i>Servicing</i> SCANIA</p>	 <p>Pictures coming soon</p> <p>75 1224</p> <p><i>Replacing</i> 0433171224 DLLA152P313 479444</p> <p><i>Servicing</i> VOLVO F10, FL10, NL10, VOLVO BM, VOLVO PENTA</p>
 <p>Pictures coming soon</p> <p>75 1237</p> <p><i>Replacing</i> 0433171237 DLLA152P335 478683</p> <p><i>Servicing</i> VOLVO B12, F12, NL12</p>	 <p>Pictures coming soon</p> <p>75 1296</p> <p><i>Replacing</i> 0433171296 DLLA153P413</p> <p><i>Servicing</i> DAF 75.300ATI RS222M</p>	 <p>Pictures coming soon</p> <p>75 1299</p> <p><i>Replacing</i> 0433271299 DLLA150S616 232612</p> <p><i>Servicing</i> SCANIA</p>
 <p>Pictures coming soon</p> <p>75 1300</p> <p><i>Replacing</i> 0433171299 DLLA142P419</p> <p><i>Servicing</i> Mercedes-Benz OM445, OM446</p>	 <p>Pictures coming soon</p> <p>75 1306</p> <p><i>Replacing</i> 0433271306 DLLA25S627 51101020141</p> <p><i>Servicing</i> MAN RENAULT</p>	 <p>Pictures coming soon</p> <p>75 1322</p> <p><i>Replacing</i> 0433271322 DLLA28S656 02145081</p> <p><i>Servicing</i> CLASS,IVECO,KHD, DEUTZ</p>
 <p>Pictures coming soon</p> <p>75 1326</p> <p><i>Replacing</i> 0433171326 DLLA152P452 51101020221</p> <p><i>Servicing</i> MAN</p>	 <p>Pictures coming soon</p> <p>75 1334</p> <p><i>Replacing</i> 0433271334 DLLA30S678 51101020146</p> <p><i>Servicing</i> MAN</p>	 <p>Pictures coming soon</p> <p>75 1358</p> <p><i>Replacing</i> 0433171358 DLLA152P496 1360009</p> <p><i>Servicing</i> SCANIA</p>

**75 1376**


Replacing 0433271376
DLLA149S774

Servicing Bomag, Fendt, Fuchs,
KHD, Kramer

**75 1394**


Replacing 0433271394
DLLA150S781

Servicing Mercedes-Benz OM355

**75 1398**


Replacing 0433171398
DLLA147P538
1364500

Servicing SCANIA

**75 1414**


Replacing 0433171414
DLLA152P566
51 10102 0233

Servicing MAN

**75 1423**


Replacing 0433271423
DLLA144S829

Servicing Mercedes-Benz OM421,
OM422, OM423, OM424,
OM407

**75 1432**


Replacing 0433171432
DLLA152P571
8194095

Servicing VOLVO B10, B10M, FL10,
FM10, NL10

**75 1434**


Replacing 0433171434
DLLA150P573
1375440

Servicing SCANIA

**75 1440**


Replacing 0433171440
DLLA 146 P 581

Servicing MAN

**75 1450**


Replacing 0433171450
DLLA154P596

Servicing Mercedes-Benz OM541,
OM542, Actros

**75 1454**


Replacing 0433171454
DLLA145P606

Servicing Cummins

**75 1455**













Replacing 0433171901
DLLA152P1454


Servicing DAF

**75 1462**

Replacing 0433271462
DLLA150S935


Servicing Kaelble, Mercedes-Benz
OM355

 <p>Pictures coming soon</p> <p>75 1470</p> <p><i>Replacing</i> 0433171470 DLLA150P635 1380777</p> <p><i>Servicing</i> SCANIA</p>	 <p>Pictures coming soon</p> <p>75 1487</p> <p><i>Replacing</i> 0433271487 DLLA136S1034</p> <p><i>Servicing</i> Mercedes-benz OM441, OM442</p>	 <p>Pictures coming soon</p> <p>75 1524</p> <p><i>Replacing</i> 0433271524 DLLA134S1199</p> <p><i>Servicing</i> Mercedes-benz OM440, 441, 442</p>
 <p>Pictures coming soon</p> <p>75 1562</p> <p><i>Replacing</i> 0433171562 DLLA155P822</p> <p><i>Servicing</i> RENAULT 420PREMIUM ROUTE</p>	 <p>Pictures coming soon</p> <p>75 1564</p> <p><i>Replacing</i> 0433171564 DLLA140P826</p> <p><i>Servicing</i> IVECO EuroCargo, EuroTech, EuroStar, EuroTrakker, Stralis</p>	 <p>Pictures coming soon</p> <p>75 1575</p> <p><i>Replacing</i> 0433171575 DLLA150P847 1409192</p> <p><i>Servicing</i> SCANIA</p>
 <p>Pictures coming soon</p> <p>75 1576</p> <p><i>Replacing</i> 0433171576 DLLA150P848 1412401</p> <p><i>Servicing</i> SCANIA</p>	 <p>Pictures coming soon</p> <p>75 1583</p> <p><i>Replacing</i> 0433171583 DLLA154P866 51 10102 0252</p> <p><i>Servicing</i> MAN</p>	 <p>Pictures coming soon</p> <p>75 1584</p> <p><i>Replacing</i> 0433171584 DLLA155P872</p> <p><i>Servicing</i> VOLVO V12, FH12, FL12</p>
 <p>Pictures coming soon</p> <p>75 1592</p> <p><i>Replacing</i> 0433171592 DLLA155P885</p> <p><i>Servicing</i> KHD</p>	 <p>Pictures coming soon</p> <p>75 1594</p> <p><i>Replacing</i> 0433171594 DLLA156P889</p> <p><i>Servicing</i> Mercedes-benz 208 CDI SPRINTER,308 CDI SPRINTER,408 CDI SPRINTER, OM611.987 DE LA</p>	 <p>Pictures coming soon</p> <p>75 1600</p> <p><i>Replacing</i> 0433171600 DLLA152P903</p> <p><i>Servicing</i> VOLVO FH12, FM12</p>

**75 1616**


Replacing 0433171616
DLLA145P926

Servicing BMW 330D
330XD, 530D, 730D X5 3.0D
LAND ROVER: RANGER
ROVER III 3.0 TD6 AWD

**75 1617**


Replacing 0433171617
DLLA145P927

Servicing BMW 525D

**75 1618**


Replacing 0433271616
DLLA143S1302

Servicing IVECO, NEWHOLLAND,
URAL AUTOMOBIL PLANT

**75 1628**


Replacing 0433171628
DLLA150P943

Servicing Mercedes-Benz Actros,
O530, OM541, OM542,
OM457

**75 1631**


Replacing 0433171631
DLLA140P947

Servicing IVECO EuroStar,
EuroTrakker, Stralis,
Trakker

**75 1634**


Replacing 0433171634
DLLA150P957

Servicing Mercedes-Benz Actros
OM541, OM542

**75 1640**


Replacing 0433171640
DLLA152P967

Servicing MAN, NEOPLAN

**75 1654**


Replacing 0433171654
DLLA150P1011

Servicing HYUNDAI, KIA

**75 1655**


Replacing 0433271655
DLLA150S1238

Servicing DAF

**75 1678**


Replacing 0433271678
DLLA148S1204
1556159

Servicing VOLVO

**75 1679**













Replacing 0433171679
DLLA147P1048


Servicing Mercedes-Benz Atego,
Axor, Econic, Conecto,
Tourino, Citaro, OM906

**75 1690**

Replacing 0433171696
DLLA142P1070


Servicing Mercedes-Benz

 <p>Pictures coming soon</p> <p>75 1695</p> <p><i>Replacing</i> 0433171695 DLLA143P1069</p> <p><i>Servicing</i> RENAULT</p>	 <p>Pictures coming soon</p> <p>75 1699</p> <p><i>Replacing</i> 0433171699 DLLA150P1076</p> <p><i>Servicing</i> RENALUT 370 KERAX, PREMIUM</p>	 <p>Pictures coming soon</p> <p>75 1702</p> <p><i>Replacing</i> 0433271702 DLLA145S1161 1207730</p> <p><i>Servicing</i> DAF F95</p>
 <p>Pictures coming soon</p> <p>75 1703</p> <p><i>Replacing</i> 0433271703 DLLA145S1160 1207731</p> <p><i>Servicing</i> DAF F95</p>	 <p>Pictures coming soon</p> <p>75 1712</p> <p><i>Replacing</i> 0433171712 DLLA156P1107</p> <p><i>Servicing</i> MB SPRINTER</p>	 <p>Pictures coming soon</p> <p>75 1714</p> <p><i>Replacing</i> 0433271714 DLLA150S1137 4851447</p> <p><i>Servicing</i> IVECO</p>
 <p>Pictures coming soon</p> <p>75 1717</p> <p><i>Replacing</i> 0433271717 DLLA140S1117 066130</p> <p><i>Servicing</i> DAF F95</p>	 <p>Pictures coming soon</p> <p>75 1718</p> <p><i>Replacing</i> 0433271718 DLLA140S1116 066131</p> <p><i>Servicing</i> DAF F95</p>	 <p>Pictures coming soon</p> <p>75 1724</p> <p><i>Replacing</i> 0433171724 DLLA150P1120 0050173921</p> <p><i>Servicing</i> Mercedes-Benz</p>
 <p>Pictures coming soon</p> <p>75 1739</p> <p><i>Replacing</i> 0433171740 DLLA150P1163</p> <p><i>Servicing</i> Mercedes-Benz Actros, OM541, OM542</p>	 <p>Pictures coming soon</p> <p>75 1740</p> <p><i>Replacing</i> 0433271740 DLLA136S943 51101020189</p> <p><i>Servicing</i> MAN</p>	 <p>Pictures coming soon</p> <p>75 1741</p> <p><i>Replacing</i> 0433171741 DLLA150P1164</p> <p><i>Servicing</i> Mercedes-Benz Axor, Actros, O500, O530, O345, OM457, OM541, OM542</p>

**75 1743**


Replacing 0433171743
DLLA151P1169

Servicing VOLVO EC2108, VOLVO L70E

**75 1774**


Replacing 0433171774
DLLA150P1224

Servicing Fiat Suzuki

**75 1783**


Replacing 0433271783
DLLA138S983
511021020192

Servicing Mercedes-benz MAN

**75 1799**


Replacing 0433171799
DLLA150P126

Servicing SCANIA

**75 1800**


Replacing 0433171800
DLLA153P1270

Servicing Mercedes-Benz E200, E220, E270, E320

**75 1811**


Replacing 0433171811
DLLA146P1296+

Servicing Nissan, Opel, Renault, Vauxall

**75 1823**


Replacing 0433271823
DLLA150S870
670957

Servicing DAF F2800 2900 3200
3300 3600 N2800

**75 1829**


Replacing 0433271829
DLLA150S853
313510

Servicing SCANIA

**75 1831**


Replacing 0433171831
DLLA146P1339

Servicing MAN

**75 1837**


Replacing 0433271837
DLLA150S838
303739

Servicing SCANIA

**75 1848**


Replacing 0433171848
DLLA156P1368

Servicing Hyundai, Kia


**75 1855**

Replacing 0433171855
DLLA140P1377


Servicing IVECO DAILY 35C14,
DAILY 40C14, DAILY
50C14


75 1865


Replacing 0433271865
DLLA150S762
467654
Servicing VOLVO


75 1878


Replacing 0433171878
DLLA144P1417
Servicing MAN TGA


75 1889


Replacing 0433171889
DLLA150P1437
Servicing Suzuki Splash, Swift


75 1904


Replacing 0433171904
216.1112010
Servicing KAMAZ 43253 53229
65115 6520 65201 740.31
-240 740.60-360


75 1905


Replacing 0433171905
905.1112110
Servicing KAMAZ 740.51-320


75 1913


Replacing 0433171913
DLLA156P1473
Servicing Mercedes-Benz C200,
C220, C270, E200, E220,
E270


75 1914


Replacing 0433171914
DLLA149P1471/
Servicing CITROEN Berlingo 1.6 HDI C3
1.6 HDI PEUGEOT 207 1.6HDI
307 1.6 HDI 308 HDI
PARTNER 1.6 HDI


75 1921


Replacing 0433171921
DLLA155P1493
DLLA150P1011
Servicing Ford, Mazda


75 1931


Replacing 0433171931
DLLA156P1509
Servicing Hyundai, Kia, Renault


75 1932


Replacing 0433171932
DLLA150P1511
Servicing Hyundai Kia


75 1933

Replacing 0433171933
DLLA150P1512
Servicing Hyundai



75 1937

Replacing 0433171937
DLLA145P1517
Servicing Iveco Stralis, Trakker

**75 1939**


Replacing 0433171939
DLLA148P1524+

Servicing MAN, NEOPLAN, TEMSA

**75 1940**


Replacing 0433171940
DLLA152P1525

Servicing Mahindra Scorpio

**75 1946**


Replacing 0433171946
DLLA145P1534

Servicing Iveco Stralis, New Holland T9

**75 1948**


Replacing 0433171948
DLLA154P1538

Servicing Mercedes-benz

**75 1952**


Replacing 0433171952
DLLA145P1543
1731907

Servicing SCANIA

**75 1958**


Replacing 0433171958
DLLA145P1552
1548477

Servicing SCANIA

**75 1959**


Replacing 0433171959
DLLA145P1556
1548474

Servicing SCANIA

**75 1965**


Replacing 0433171965
DLLA150P1566

Servicing VOLVO FE240, FE280,
FE320, FL240, FL280,
FL320, RENAULT, KAVZ
KURGAN

**75 1968**


Replacing 0433171968
DLLA146P1581

Servicing KHD, RENAULT

**75 1972**


Replacing 0433171972
DLLA145P1594
1734825

Servicing SCANIA

**75 1980**













Replacing 0433171980
DLLA150P1606


Servicing Daewoo Opel

**75 1982**

Replacing 0433171982
DLLA153P1608

Servicing HYUNDAI OPEL

 <p>75 1986</p> <p><i>Replacing</i> 0433171986 DLLA150P1614</p> <p><i>Servicing</i> Mercedes-Benz Axor, Citro, Conecto, Integro, O500, O530, Turismo, OM457</p>	 <p>75 2004</p> <p><i>Replacing</i> 0433172004 DLLA148P1641</p> <p><i>Servicing</i> MAN, TEMSA</p>	 <p>75 2016</p> <p><i>Replacing</i> 0433172016 DLLA145P1655 612630090015</p> <p><i>Servicing</i> FOTON AUMAN 11.6D JAC HFC4118,HFC4251 WEICHAI WP10 EC3 HOWO 9.7D 11.6D SHANQI DELONG 11.6 WP12 EU3</p>
 <p>75 2021</p> <p><i>Replacing</i> 0433172021 DLLA146P1662</p> <p><i>Servicing</i> VM</p>	 <p>75 2026</p> <p><i>Replacing</i> 0433172026 DLLA155P1674</p> <p><i>Servicing</i> FAW CA4DC1 CA4DC2</p>	 <p>75 2029</p> <p><i>Replacing</i> 0433172029 DLLA152P1681</p> <p><i>Servicing</i> Mahindra Scorpio</p>
 <p>75 2036</p> <p><i>Replacing</i> 0433172036 DLLA152P1690 G2100-1112150-A38</p> <p><i>Servicing</i> KINGLONG 5.2D YUCHAI YC4E YC6J</p>	 <p>75 2042</p> <p><i>Replacing</i> 0433172042 DLLA145P1698</p> <p><i>Servicing</i> MAN Lion's City D2066</p>	 <p>75 2078</p> <p><i>Replacing</i> 0433172078 DLLA152P1768</p> <p><i>Servicing</i> WEICHAI</p>
 <p>75 2081</p> <p><i>Replacing</i> 0433172081 DLLA150P1772</p> <p><i>Servicing</i> GREAT WALL</p>	 <p>75 2084</p> <p><i>Replacing</i> 0433172084 DLLA157P1777 00751038</p> <p><i>Servicing</i> MAN TGL TGM D0836</p>	 <p>75 2094</p> <p><i>Replacing</i> 0433172094 DLLA154P1795</p> <p><i>Servicing</i> MAN, TEMSA</p>




Pictures coming soon

75 2111

Replacing 0433172111
DLLA152P1819
612600081077

Servicing WEICHAH




Pictures coming soon

75 2120

Replacing 0434250120
DN0SD261

Servicing Mercedes-benz 190D, 200TD, 207D,
209D, 240D, 300GD, 307D, 309D,
407D, 409D, E200, MB100, MB120,
MB140, MB160, MB180, MB90




Pictures coming soon

75 2128

Replacing 0434250128
DN0SD265

Servicing Mercedes-benz Sprinter
OM601 OM602




Pictures coming soon

75 2178

Replacing 0433172178
DLLA154P2178

Servicing Mercedes-benz




Pictures coming soon

75 2203

Replacing 0433172203
DLLA118P2203

Servicing CUMMINS, KOMATSU




Pictures coming soon

75 2273

Replacing 0433172273
DLLA144P2273

Servicing CUMMINS ISC, ISLE




Pictures coming soon

75 5163

Replacing 0433175163
DSLA156P736

Servicing Mercedes-benz C200 CDI,
C220 CDI E200 CDI




Pictures coming soon

75 5164

Replacing 0433175164
DSLA156P737

Servicing Mercedes-benz




Pictures coming soon

75 5175

Replacing 0433175175
DSLA145P763

Servicing Fiat




Pictures coming soon

75 5196

Replacing 0433175196
DSLA142P795

Servicing CHEVROLET, CITROEN,
FIAT, LANCIA, PEUGEOT,
SUZUKI




Pictures coming soon

75 5202

Replacing 0433175202
DSLA153P803

Servicing CUMMINS
















Pictures coming soon

75 5203

Replacing 0433175203
DSLA136P804
5600684095

Servicing RENAULT IVECO FIAT
CITRON

 <p>Pictures coming soon</p> <p>75 5230</p> <p><i>Replacing</i> 0433165230 DSLA140P862+</p> <p><i>Servicing</i> Renault</p>	 <p>Pictures coming soon</p> <p>75 5253</p> <p><i>Replacing</i> 0433175253 DSLA145P896+</p> <p><i>Servicing</i> Renault</p>	 <p>Pictures coming soon</p> <p>75 5268</p> <p><i>Replacing</i> 0433175268 DSLA154P960</p> <p><i>Servicing</i></p>
 <p>Pictures coming soon</p> <p>75 5271</p> <p><i>Replacing</i> 0433175271 DSLA143P970</p> <p><i>Servicing</i> IVECO EUROARGO 3.9/5.9 2000 - PRESENT DAF LC / LF FORD CARGO 3.9/5.9 2005 - PRESENT NEW HOLLAND T7060 6.7 2007 - PRESENT VOLKSWAGEN CONSTELLATION 5.9 2005 - PRESENT</p>	 <p>Pictures coming soon</p> <p>75 5278</p> <p><i>Replacing</i> 0433175278 DSLA145P979</p> <p><i>Servicing</i> Opel Renault</p>	 <p>Pictures coming soon</p> <p>75 5298</p> <p><i>Replacing</i> 0433175298 DSLA154P1034</p> <p><i>Servicing</i> Mercedes-benz</p>
 <p>Pictures coming soon</p> <p>75 5314</p> <p><i>Replacing</i> 0433175314 DSLA156P1079/+</p> <p><i>Servicing</i> Mercedes-benz</p>	 <p>Pictures coming soon</p> <p>75 5318</p> <p><i>Replacing</i> 0433175318 DSLA145P1091</p> <p><i>Servicing</i> RENAULT MASTER 2.5DCI</p>	 <p>Pictures coming soon</p> <p>75 5326</p> <p><i>Replacing</i> 0433175326 DSLA156P1113</p> <p><i>Servicing</i> Mercedes-benz C200, C220,E200,E110,E270 OM611</p>
 <p>Pictures coming soon</p> <p>75 5342</p> <p><i>Replacing</i> 0433175342 DSLA156P1155+</p> <p><i>Servicing</i> Mercedes-benz OM668</p>	 <p>Pictures coming soon</p> <p>75 5348</p> <p><i>Replacing</i> 0433175348 DSLA145P1174</p> <p><i>Servicing</i> CASE, IVECO, NEW HOLLAND</p>	 <p>Pictures coming soon</p> <p>75 5395</p> <p><i>Replacing</i> 0433175395 DSLA154P1320</p> <p><i>Servicing</i> Mercedes-benz VITO, SPRINTER</p>




Pictures coming soon

75 5416

Replacing 0433175416
DSLA156P1411

Servicing Mercedes-Benz Atego,
Cito, Citaro, Unimog, Vario




Pictures coming soon

75 5431

Replacing 0433175431
DSLA142P1474

Servicing CITROËN BERLINGO 2.0
HDI




Pictures coming soon

75 5443

Replacing 0433175443
DSLA146P1465

Servicing ASHOK LEYLAND




Pictures coming soon

75 5449

Replacing 0433175449
DSLA128P1510

Servicing CUMMINS




Pictures coming soon

75 5450

Replacing 0433175450
DSLA143P1523

Servicing DONGFENG DAF




Pictures coming soon

75 5451

Replacing 0433175451
DSLA142P1501

Servicing Cummins




Pictures coming soon

75 5452

Replacing 0433175452
DSLA138P1505

Servicing




Pictures coming soon

75 5462

Replacing 0433175462
DSLA152P1603

Servicing MERCEDES-BENZ
ACTROS OM541




Pictures coming soon

75 5478

Replacing 0433175478
DSLA153P1710

Servicing




Pictures coming soon

75 5481

Replacing 0433175481
DSLA140P1723

Servicing CUMMINS, ISBe-4,6
KAMAZ 4308 53605,65115
KUR 4235 PAB
32301,3237,4230




Pictures coming soon

75 5484

Replacing 0433175484
DSLA150P1729

Servicing Mercedes-benz Atego,
Conecto, Toruino, Citaro,
Unimog, Vario, OM904,
OM906




Pictures coming soon

75 5501


Replacing 0433175501
DSLA143P5501

Servicing FORD CARGO ISBe4,
ISBe6 VW WORKER
INTERACT 4,6


75 5510


Replacing 0433175510
DSLA128P5510

Servicing


75 5601


Replacing 33.1112110-10

Servicing KAMAZ 4310 43101 5320
53212 5410 54112 55102
5511


78 0181

Replacing 0433270181
DLL150S919/TR

Servicing PERKINS 4.236


78 3079

Replacing 181-1112010-001

Servicing YAMZ 8401 5423 850