




Injection System Parts

Diesel Gear Pump



Tianjin Gerotor Auto Parts Co., Ltd.

2-1-1703, Luolan Garden, YongAn Rd. Hexi Dist., Tianjin, China

Web-site: www.gerotorauto.com E-mail: info@gerotorauto.com

Tel: 0086-22-23286383 Fax: 0086-22-83863296

O.E.M names and numbers are used for reference purpose only.



78 3051

Replacing 21114793


Servicing VOLVO D13C D16



78 3053

Replacing 3186357

Servicing CAT C9 Excavator



78 3060

Replacing 1903443
3848612

Servicing CST C12 C15 Kenworth
T800 Inter 9200 Peterbilt
378



78 3061

Replacing 3848611
1903442

Servicing CAT C13 C15 C18



78 3062

Replacing 2923751

Servicing CAT C6.4



78 3063

Replacing 4264806

Servicing CAT C6.6



78 3064

Replacing 1339200

Servicing DAF XF95 XF105



78 6028

Replacing 5001863917
0440020028
40817

Servicing RENAULT Premium TR PR
Midlum Kerax



78 6030

Replacing 3964833
7403964833

Servicing VOLVO D12A D12C D12D
RENAULT Magnum Dxi12



78 6031

Replacing 20769469
40884

Servicing VOLVO FH12, FH16, FM12,
FL12, NH12



78 6032

Replacing 20752310
7421067551













Servicing VOLVO D12D D12F
RENAULT Magnum Dxi12



78 6035

Replacing 5010284792
0440020035

Servicing RENAULT MAGNUM E.
TECH400

 <p>78 6036</p> <p><i>Replacing</i> 322GC49A 0440020036</p> <p><i>Servicing</i> MACK</p>	 <p>78 6042</p> <p><i>Replacing</i> 1518142 49476</p> <p><i>Servicing</i> SCANIA 4 DC-DT12</p>	 <p>78 6045</p> <p><i>Replacing</i> 51121017139 0440020045</p> <p><i>Servicing</i> MAN TGA TGL TGM TGS TGX Neoplan</p>
 <p>78 6049</p> <p><i>Replacing</i> 51121017141 0440020049 46448</p> <p><i>Servicing</i> MAN TGA D2066</p>	 <p>78 6051</p> <p><i>Replacing</i> 0040910501 48587</p> <p><i>Servicing</i> Mercedes-benz Actros Antos Arocs Axor Atego Econic OM 904 OM924 OM926 OM906</p>	 <p>78 6052</p> <p><i>Replacing</i> 4570910601 48360</p> <p><i>Servicing</i> Mercedes-benz Actros Antos Arocs Axor OM457LA OM460LA</p>
 <p>78 6053</p> <p><i>Replacing</i> 85103778 7420997341</p> <p><i>Servicing</i> VOLVO: FH13,FH16,FM9, FM13</p>	 <p>78 6054</p> <p><i>Replacing</i> 1695495</p> <p><i>Servicing</i> DAF CF85 XF95/105</p>	 <p>78 6057</p> <p><i>Replacing</i> 1539298 0440020057</p> <p><i>Servicing</i> SCANIA 114 124</p>
 <p>78 6058</p> <p><i>Replacing</i> 1536255 0440020058</p> <p><i>Servicing</i> SCANIA DC16</p>	 <p>78 6066</p> <p><i>Replacing</i> 4088866</p> <p><i>Servicing</i> CUMMINS IsI9/QsI9</p>	 <p>78 6078</p> <p><i>Replacing</i> 51121017148 0440020078</p> <p><i>Servicing</i> MAN TGA TGS TGX</p>



78 6096

Replacing 0440020095
42559145

Servicing IVECO,DFM, CASE,
KOMATSU



78 6114

Replacing 0440020114

Servicing FAW 6.6D CA6DF EU3
YUCAI YC6M EU3



78 6115

Replacing 0440020115

Servicing YUCHAI YC6L EU3



78 6125

Replacing 504140125
3898046

Servicing IVECO STRALIS



78 6330

Replacing 02113800
04503573

Servicing DEUTZ BF6M1013
BF4M2012 BF6M2012



78 6332

Replacing 04296790

Servicing DEUTZ TCD2012
TCD2013



78 6333

Replacing 04282358

Servicing DEUTZ TCD2013
TCD2012



78 6334

Replacing 04297075

Servicing DEUTZ TCD2013
TCD2012



78 6335

Replacing 04909040
21683947

Servicing DEUTZ TCD2014
TCD2013



78 6350

Replacing 23532981
R23537686

Servicing DETROIT S60



78 6351

Replacing 4570910201

Servicing Mercedes-benz