



Diesel Parts

——Unit Pump System












Tianjin Geortor Auto Parts Co., Ltd.

2-1-1703, Luolan Garden, YongAn Rd. Hexi Dist. Tianjin, China.

Web-site: www.geortorauto.com E-mail: info@geortorauto.com

Tel: 0086-22-23286383 Fax: 0086-22-83863296

O.E.M names and numbers are used for reference purpose only.

<p style="text-align: center;">Pictures coming soon</p>  <p>78 7000</p> <p><i>Replacing</i> 0414755003 5010284908 313GC5227M</p> <p><i>Servicing</i> MACK E7-350 RENAULT MAGNUM MIDR</p>	<p style="text-align: center;">Pictures coming soon</p>  <p>78 7001</p> <p><i>Replacing</i> 0414755005 1379110 1392052</p> <p><i>Servicing</i> DAF 75CF 85CF 95CF 95XF</p>	<p style="text-align: center;">Pictures coming soon</p>  <p>78 7002</p> <p><i>Replacing</i> 0414701005 1529749 1382121</p> <p><i>Servicing</i> SCANIA DSC12 DC11</p>
<p style="text-align: center;">Pictures coming soon</p>  <p>78 7004</p> <p><i>Replacing</i> 0414750004 20450666 2112706</p> <p><i>Servicing</i> Deutz BF6M1013FC VOLVO D7D EC240B</p>	 <p>78 7005</p> <p><i>Replacing</i> 0414799005 0280745902</p> <p><i>Servicing</i> MERCEDES-BENZ ACTROS AXOR CITARO INTEGRO</p>	 <p>78 7006</p> <p><i>Replacing</i> 0414799008 0280746902</p> <p><i>Servicing</i> MAZ MISK BENZ ATEGO OM906LA OM926LA FREIGHLINER</p>
<p style="text-align: center;">Pictures coming soon</p>  <p>78 7012</p> <p><i>Replacing</i> 0414702007 20440412</p> <p><i>Servicing</i> VOLVO FH12 FM12</p>	<p style="text-align: center;">Pictures coming soon</p>  <p>79 7001</p> <p><i>Replacing</i> 0414755007 5001860116</p> <p><i>Servicing</i> RENAULT MAGUNM; MACK E7 EURO 3</p>	<p style="text-align: center;">Pictures coming soon</p>  <p>79 7002</p> <p><i>Replacing</i> 0414755008 1435558</p> <p><i>Servicing</i> DAF 75CF 85CF 95XF</p>